Owner: Field to Scale | All Buildings | Generated 10/29/2026

Punch List Dashboard

Current building-by-building field punch status

6	5	1	5
TOTAL ITEMS	OPEN	COMPLETE	BUILDINGS

Building Status

Building A	2 open | 2 total	0% complete
Building B	0 open | 1 total	100% complete
Building C	1 open | 1 total	0% complete
Clubhouse	1 open | 1 total	0% complete
Site	1 open | 1 total	0% complete

CONTRACTOR USE

Review every open item, complete the corrective work, and provide photo evidence.

When shared from Field to Scale, an editable Excel copy is included as a separate file.

Owner: Field to Scale | All current punch items | Generated 10/29/2026

ID	Building	Location	Responsible	Punch Item	Status
01	Building A	Level 2	Paint	Paint touch-up at unit 204 entry	**Open**
02	Building A	Level 2	Electrical	Missing outlet cover, kitchen	**Open**
03	Building B	Level 2	Doors / Hardware	Door closer adjustment	**Complete**
04	Clubhouse	Level 2	Flooring	Grout haze at restroom floor	**Open**
05	Building C	Level 2	GC	Caulk gap at tub surround	**In Progress**
06	Site	Level 2	Site	Sidewalk spall at front walk	**Open**

Owner: Field to Scale | 1-2 of 6 items

01 | Building A

Open

Paint touch-up at unit 204 entry

FIELD CONDITION

No punch photo

Location: Level 2

Responsible: Paint

Item date: 2026-10-20 | 9 days open

02 | Building A

Open

Missing outlet cover, kitchen

FIELD CONDITION

No punch photo

Location: Level 2

Responsible: Electrical

Item date: 2026-10-20 | 9 days open

Owner: Field to Scale | 3-4 of 6 items

03 | Building B

Complete

Door closer adjustment

FIELD CONDITION

No punch photo

Location: Level 2

Responsible: Doors / Hardware

Item date: 2026-10-20 | Complete

04 | Clubhouse

Open

Grout haze at restroom floor

FIELD CONDITION

No punch photo

Location: Level 2

Responsible: Flooring

Item date: 2026-10-20 | 9 days open

Owner: Field to Scale | 5-6 of 6 items

05 | Building C

In Progress

Caulk gap at tub surround

FIELD CONDITION

No punch photo

Location: Level 2

Responsible: GC

Item date: 2026-10-20 | 9 days open

06 | Site

Open

Sidewalk spall at front walk

FIELD CONDITION

No punch photo

Location: Level 2

Responsible: Site

Item date: 2026-10-20 | 9 days open